



Oil Companies International Marine Forum

Offshore Vessels Inspection Database (OVID)

OVIQ

Report Number	XNLR-4597-8496-4419
Report Template	OVIQ2 (7105)
Vessel Name	SMS Valiant
IMO Number	9581394
Date of Inspection	16 Sep 2015
Port of Inspection	Kali Baru Jetty Marunda, Jakarta
Inspecting Company	Chevron Shipping Co. LLC

PPE MATRIX

(COMPANY PPE REQUIREMENT FOR SPECIFIC SHIPBOARD TASK)

NATURE OF WORK	PROTECTIVE & PREVENTIVE MEASURES REQUIRED										
	HIGH IMPACT GLOVE	SAFETY HELMET	SAFETY GOOGLE	EAR MUFF, EAR PLUG	WELDING MASK	SAFETY SHOES	SAFETY HARNESS	RING BUOY, LIFE JACKET	COVERALL, BOILER SUIT	POSITIVE PRESSURE SCBA, MASK REGULATOR	ADDITIONAL
Chemical Handling	1	2	1		1	1				2	Apron may be required
Clearing, Heavy Duty	1	2	1		2	1				2	Long sleeved coveralls
Clearing, Light Duty	1	2	1			1					
Deck Work, Anchor Handling	1	1	1	2		1		1	1		
Deck Work, General	1	1	1	2		1			1		
Deck Work, Tending Pilot	1	1	1	2		1		1	1		
Electrical Work	1	2	1	2		1			2		Insulating mat may be required
Enclosed Space Entry	1	1	2	2		1	2		2	2	Long sleeved coveralls
Food Preparation	1					1					Apron may be required
Hot Work	1	2	1	2	2	1					
Machinery Spaces, General work	1	2	1	1		1			2		
Using Manual Tools	1	2	1	2		1					
Using Power Tools	1	2	1	2	1	1					
Welding	1	2	1	2	1	1				2	Apron and spats required
Working at Height	1	1	1	2		1	1	2	2		Tool Belt required
Working Overseide	1	1	1	2		1	1	1	2		Tool Belt required

1 = **Mandatory**

2 = **As determined by risk assessment, company procedures or by the nature of the work**

Reference : SBM section 3.6