



Oil Companies International Marine Forum

Offshore Vessels Inspection Database (OVID)

OVIQ

Report Number	XNLR-4597-8496-4419
Report Template	OVIQ2 (7105)
Vessel Name	SMS Valiant
IMO Number	9581394
Date of Inspection	16 Sep 2015
Port of Inspection	Kali Baru Jetty Marunda, Jakarta
Inspecting Company	Chevron Shipping Co. LLC

Section D: Daily Radio Function Log

Radio Log Book (GMDSS)	Vessel Name: SMS VALIANT	Call Sign: YDA 4811	MMSI: 525019582
------------------------	--------------------------	---------------------	-----------------

Date & Time (UTC)	Station to	Station from	Operators Actions/Remarks (Summary)	Frequency, Channel or Satellite	GMDSS/Operator
16.09.2015 10:00	All STATION	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
17.09.2015 09:30	All STATION	P2 GMDSS	Station Radio check	CH. 16	PURDIYANTO
18.09.2015 11:29	All STATION	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
19.09.2015 09:40	All STATION	P2 GMDSS	Station Radio Check weekly test MF/HF. VHF found good	CH. 16, 12, 14	PURDIYANTO
20.09.2015 19:12	All STATION	P2 GMDSS	Station Radio Check	CH. 16	PURDIYANTO
21.09.2015 07:45	All STATION	P2 GMDSS	Station Radio Check	CH. 16	PURDIYANTO
22.09.2015 09:16	All STATION	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
23.09.2015 10:41	All STATION	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
24.09.2015 09:06	All STATION	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
25.09.2015 10:30	All STATION	P2 GMDSS	Station Radio check	CH. 16	PURDIYANTO
26.09.2015 09:00	All Station	P2 GMDSS	Station Radio Check weekly test MF/HF. VHF found good	CH. 16, 12, 14	YANTO S.
27.09.2015 11:00	All Station	P2 GMDSS	Station Radio Check	CH. 16	YANTO S.
28.09.2015 16:30	All Station	P2 GMDSS	Station Radio check	CH. 16	YANTO S.
29.09.2015 09:00			Month check and test.		YANTO & PURDIYANTO
			EPRB found good condition		
			SART found good condition with Radar		
			survival craft two way VHF found good condition		
			Antena & Battery charge found good condition		
29.09.2015 09:30	All station	P2 GMDSS	Station Radio check	CH 16	YANTO & PURDIYANTO